Annual Environmental Report

2020



Castletownshend

D0468-01

CONTENTS

1 EXECUTIVE SUMMARY AND INTRODUCTION TO THE 2020 AER

- 1.1 ANNUAL STATEMENT OF MEASURES
- 1.2 Treatment Summary
- 1.3 ELV OVERVIEW
- 1.4 LICENSE SPECIFIC REPORT INCLUDED IN AER

2 TREATMENT PLANT PERFORMANCE AND IMPACT SUMMARY

- 2.1 Castletownshend Untreated Discharge 2020 Untreated Discharge
 - 2.1.1 EFFLUENT MONITORING SUMMARY CASTLETOWNSHEND UNTREATED DISCHARGE 2020 -
 - 2.1.2 Ambient Monitoring Summary for Untreated Discharge -

3 COMPLAINTS AND INCIDENTS

- 3.1 COMPLAINTS SUMMARY
- 3.2 REPORTED INCIDENTS SUMMARY
 - 3.2.1 SUMMARY OF INCIDENTS
 - 3.2.2 Summary of Overall Incidents

4 INFRASTRUCTURAL ASSESSMENT AND PROGRAMME OF IMPROVEMENTS

- 4.1 STORM WATER OVERFLOW IDENTIFICATION AND INSPECTION REPORT
 - 4.1.1 SWO IDENTIFICATION AND INSPECTION SUMMARY REPORT
 - 4.2 REPORT ON PROGRESS MADE AND PROPOSALS BEING DEVELOPED TO MEET THE IMPROVEMENT PROGRAMME REQUIREMENTS
 - 4.2.1 Specified Improvement Programme Summary
 - 4.2.2 IMPROVEMENT PROGRAMME SUMMARY
 - 4.2.3 SEWER INTEGRITY RISK ASSESSMENT

5 LICENCE SPECIFIC REPORTS

5.1 Priority Substances Assessment

6 CERTIFICATION AND SIGN OFF

6.1 Summary of AER Contents

7 APPENDIX

7.1 Ambient monitoring summary

1 EXECUTIVE SUMMARY AND INTRODUCTION TO THE 2020 AER

This Annual Environmental Report has been prepared for D0468-01, Castletownshend, in Cork in accordance with the requirements of the wastewater discharge licence for the agglomeration. Specified reports where relevant are included as an appendix to the AER.

1.1 ANNUAL STATEMENT OF MEASURES

A summary of any improvements undertaken is provided where applicable.

New WWTP for Castletownsend is currently at planning stage

1.2 TREATMENT SUMMARY

• Currently there is no treatment provided at Castletownshend . Please refer to section 4 for details of the Programme of Improvements.

1.3 ELV OVERVIEW

The overall compliance of the final effluent with the Emission Limit Values (ELVs) is shown below. More detailed information on the below ELV's can be found in Section 2.

Discharge Point Treatment Plant		Discharge Type	Compliance Status	Parameters failing if relevant	
TPEFF0500D0468SW001	Castletownshend Untreated Discharge - 2020	Untreated	No influent monitoring undertaken therefore % reduction compliance cannot be determined.	N/A	

1.4 LICENCE SPECIFIC REPORTING INCLUDED IN AER

Assessment / Report	Included in AER
There are no Licence Specific Reports included in the AER.	

2 TREATMENT PLANT PERFORMANCE AND IMPACT SUMMARY

2.1.1 EFFLUENT MONITORING SUMMARY -

Parameter	WWDL ELV (Schedule A)	ELV with Condition 2 Interpretation included Note 1	Interim % reduction from influent concentration	Number of sample results	Number of exceedances	Number of with Condition 2 Interpretation included	Annual Mean	Overall Compliance (Pass/Fail)
COD-Cr mg/l	N/A	N/A	N/A	6	N/A	N/A	24.83	Unknown
Suspended Solids mg/l	N/A	N/A	N/A	6	N/A	N/A	8.17	Unknown
BOD, 5 days with Inhibition (Carbonaceous BOD) mg/l	N/A	N/A	N/A	6	N/A	N/A	5.17	Unknown

Notes:

Cause of Exceedance(s):

Not applicable

Significance of Results:

The WWTP is non-compliant with the ELV's set in the Wastewater Discharge Licence.

^{1 –} This represents the Emission Limit Values after the Interpretation provided for under Condition 2 of the licence is applied

2.1.2 AMBIENT MONITORING SUMMARY FOR THE UNTREATED DISCHARGE TPEFF0500D0468SW001

A summary of monitoring from ambient monitoring points associated with the wastewater discharge is provided in the sections below. For discharges to rivers upstream (U/S) and downstream (D/S) location data is provided. For other ambient points in lakes, coastal or transitional waters, monitoring data from the most appropriate monitoring station is selected.

The table below provides details of ambient monitoring locations and details of any designations as sensitive areas.

Ambient Monitoring Point from WWDL (or as agreed with EPA)	Irish Grid Reference	River Station Code	Bathing Water	Drinking Water	FWPM	Shellfish	WFD Status
Downstream	118659, 30973	CW05003177RY1001	No	No	No	No	Unassigned

The results for ambient results and / or additional monitoring data sets are included in the Appendix 7.1 - Ambient monitoring summary

Significance of Results:

The WWTP discharge was non-compliant with the ELV's set in the wastewater discharge licence.

The ambient monitoring results does not meet the required EQS. The EQS relates to the Oxygenation and Nutrient Conditions set out in the Surface Water Regulations 2009.

The discharge from the wastewater treatment plant does not have an observable impact on the water quality.

A deterioration in water quality has been identified, however it is not known if it or is not caused by the WWTP.

Other causes of deterioration in water quality in the area are: Catchment pressures

The discharge from the wastewater treatment plant does not have an observable negative impact on the Water Framework Directive status.

3 COMPLAINTS AND INCIDENTS

3.1 COMPLAINTS SUMMARY

A summary of complaints of an environmental nature is included below.

Number of Complaints	Nature of Complaint	Number Open Complaints	Number Closed Complaints
There were no relevant environme	ental complaints in 2020.		

3.2 REPORTED INCIDENTS SUMMARY

Environmental incidents that arise in an agglomeration are reported on an on-going basis in accordance with our waste water discharge licences. Where an incident occurs and it is reportable under the licence, it is reported to the Environmental Protection Agency through their Environmental Data Exchange Network, or in some instances by telephone. Some incidents which arise in the agglomeration are recorded by Irish Water but may not be reportable under our licence for example where the incident does not have an impact on environmental performance.

A summary of reported incidents is included below.

3.2.1 SUMMARY OF INCIDENTS

Incident Type Cause		No. of incident occurrences	Recurring (Y/N)	Closed (Y/N)	
There were no reportable	incidents in 20	220.			

3.2.2 SUMMARY OF OVERALL INCIDENTS

Question	Answer
Number of Incidents in 2020	0
Number of Incidents reported to the EPA via EDEN in 2020	0
Explanation of any discrepancies between the two numbers above	N/A

4 INFRASTRUCTURAL ASSESSMENTS AND PROGRAMME OF IMPROVEMENTS

4.1 STORM WATER OVERFLOW IDENTIFICATION AND INSPECTION REPORT

A summary of the operation of the storm water overflows and their significance where known is included below:

4.1.1 SWO IDENTIFICATION

WWDL Name / Code for Storm Water Overflow	Irish Grid Ref.	Included in Schedule A4 of the WWDL	Significance of the overflow(High / Medium / Low)	Assessed against DoEHLG Criteria	No. of times activated in 2020 (No. of events)	Total volume discharged in 2020 (m3)	Monitoring Status		
There are no Storm Water Overflows in this Agglomeration.									

SWO Summary				
How much sewage was discharged via SWOs in the agglomeration in the year (m3)?	Unknown			
Is each SWO identified as not meeting DoEHLG Guidance included in the Programme of Improvements?				
The SWO Assessment included the requirements of relevant of WWDL schedules?	N/A			
Have the EPA been advised of any additional SWOs / changes to Schedule C3 and A4 under Condition 1.7?	N/A			

4.2 REPORT ON PROGRESS MADE AND PROPOSALS BEING DEVELOPED TO MEET THE IMPROVEMENT PROGRAMME REQUIREMENTS.

4.2.1 SPECIFIED IMPROVEMENT PROGRAMME SUMMARY

A wastewater discharge licence may require a number of reports on specific subject areas to be prepared for the agglomeration in question. These reports are submitted to the EPA as part of the Annual Environmental Report. This section provides list of the various reports required for this agglomeration and a brief summary of their recommendations.

Specified Improvement Programmes (under Schedule A and C of WWDL)	Description	Licence Schedule	Licence Completion Date	Date Expired? (N/NA/Y)	Status of Works	Timeframe for Completing the Work	Comments
D0468-SIP:01	Discontinue discharge from SW02 CEND	А	22/12/2015	Yes	Not Started	31/12/2024	
D0468-SIP:02	Extension of primary discharge outfall	С	22/12/2015	Yes	At Planning Stage	31/12/2024	
D0468-SIP:03	Foul sewer upgrade and extension (to include the separation of surface water and the connection of the 8 No. Houses on Western Quay).	С	22/12/2015	Yes	At Planning Stage	31/12/2024	

Specified Improvement Programmes (under Schedule A and C of WWDL)	Description	Licence Schedule	Licence Completion Date	Date Expired? (N/NA/Y)	Status of Works	Timeframe for Completing the Work	Comments
D0468-SIP:04	Waste water treatment plant and ancillary works	С	22/12/2015	Yes	At Planning Stage	31/12/2024	

A summary of the status of any improvements identified by under Condition 5.2 is included below.

4.2.2 IMPROVEMENT PROGRAMME SUMMARY

	provement entifier	Improvement Description / or any Operational Improvements	Improvement Source	Expected Completion Date	Comments
Th	nere are no Improvem	nents Programme for this Agglomeration.			

4.2.3 SEWER INTEGRITY RISK ASSESSMENT

N/A

5 LICENCE SPECIFIC REPORTS

A wastewater discharge licence may require a number of reports on specific subject areas to be prepared for the agglomeration in question. These reports are submitted to the EPA as part of the Annual Environmental Report. This section provides list of the various reports required for this agglomeration and a brief summary of their recommendations.

5.a Licence Specific Reports Summary Table

Li	cence Specific Report	Required by licence	Year included in AER	Included in this AER	Reference to relevant section of AER
Р	riority Substances Assessment	Yes	2015	No	

5.1 PRIORITY SUBSTANCES ASSESSMENT

The Priority Substances Assessment Report has been included in the AER 2015

6 CERTIFICATION AND SIGN OFF

6.1 SUMMARY OF AER CONTENTS

Parameter	Answer
Does the AER include an Executive Summary?	Yes
Does the AER include an assessment of the performance of the Waste Water Works (i.e. have the results of assessments been interpreted against WWDL requirements and or Environmental Quality Standards)?	Yes
Is there a need to advise the EPA for consideration of a Technical Amendment / Review of the licence?	No
List reason e.g. additional SWO identified	N/A
Is there a need to request/advise the EPA of any modification to the existing WWDL with respect to condition 4 changes to monitoring location, frequency etc	No
List reason e.g. changes to monitoring requirements	N/A
Have these processes commenced?	N/A
Are all outstanding reports and assessments from previous AERs included as an appendix to this AER	Yes

I certify that the information given in this Annual Environmental Report is truthful, accurate and complete:

Signed: Date: 31/03/2021

This AER has been produced by Irish Water's Environmental Information System (EIMS) and has been electronically signed off in that system for and on behalf of ,

Katherine Walshe

Acting Head of Environmental Regulation.

7 APPENDIX

Appendix

Appendix 7.1 - Ambient monitoring summary

Castletownsend Ambient	E	QS					95%ile	Mean
	Mean	95%ile	05/02/2020 13:40	03/06/2020 11:30	05/08/2020 09:50	07/10/2020 11:35		
D.O % O ₂	80%<95%	%ile<120%	105.2	133.7		100.1	130.85	113
Temperature C°	≤ 1.5 C ^o	increase	12.1	17.1		13.5	16.74	14.233333
pH	6 < p	oH < 9	7.8	8.2	8	8	8.17	8
BOD mg/L	N	I/A	1.6	1	1.4	1.1	1.57	1.275
Orthophosphate (P) mg/l	N	I/A	0.02	0.005	0.005	0.08	0.071	0.0275
Ammonia (N) mg/l	N	I/A	0.0175	0.0175	0.0175	0.268	0.230425	0.080125
DIN (N) mg/l	≤ 0.25 €	② 34 PSU	0.183	0.0175	0.068	0.555	0.4992	0.205875
TON (N) mg/l	≤ 0.25 @	② 34 PSU	0.24	0.01	0.07	0.35	0.3335	0.1675
Faecal Coliforms MPN/100mls	N	I/A	10	31	145	15531	13223.1	3929.25
E.Coli MPN/100mls	N	I/A	5	20	121	5012	4278.35	1289.5
Intestinal enterococci CFU/100mls	N	I/A	5	10	85	520	454.75	155

Ambient Monitoring Point from WWDL		EPA Feature Coding					Current WFD
(or as agreeded with EPA)	Irish Grid Reference	tool Code	Bathing Water	Drinking Water	FWPM	Shellfish	Status
Downstream Monitoring Point	E118659 N30973	CW05003177RY1001	No designated	No	No	No	Unassigned

Significance of Results	
Did the ambient monitoring results meet the EQS Required?	No
Is there an obervable negative impact on water quality?	Yes
List the parameters causing the impact?	DO, DIN and TO
A deterioration has been identified, but it is not known if it is caused by the TP	TRUE
Do the discharges from the WWTP have an observable negative impact on the WFD?	Possibly
Any other known impacts	Catchment Press

